

# TIMKEN®

## THE TIMKEN COMPANY

GENERAL OFFICES  
CANTON, OHIO, U.S.A. 44706-2798  
TELEPHONE: (216) 438-3000

US EPA RECORDS CENTER REGION 5



494517

February 28, 1989

Mr. Kelvin F. Rogers  
Environmental Scientist  
Division of Water Pollution Control  
Ohio Environmental Protection Agency  
2110 East Aurora Road  
Twinsburg, OH 44087-1969

RE: Ohio EPA Permit No. 3ID00021\*DD  
NPDES Permit No. OH0004219

Dear Mr. Rogers:

I am writing in regard to your letter of February 15, 1989 concerning the monthly monitoring reports for our outfalls 007 and 017. Upon investigation, entries for 007 on December 14, 1988 and 017 on December 28, 1988 should have been "No Flow." It seems that either the sampler did not communicate to the lab analyst or the analyst did not enter the fact into the computer.

I have instructed the sampler and lab analyst as to the proper reporting procedures and specifically as to communicating and reporting "No Flow" situations.

If you have any questions, please contact me.

Sincerely,

William E. Lacure  
Environmental Control  
Coordinator

rjm/B:305.wel

RECEIVED

MAR 01 1989

OHIO EPA-N.E.D.O.